



Revision
06/28/11

2RZ/3RZ Teflon Throttle Body Gasket (Part #1032099)

On the Teflon throttle body gasket there is a small notch cut out of the center hole of the gasket. This notch must be installed as shown below. Failure to install it properly will result in running issues.




2031 Holly Avenue, Lake Havasu City, AZ 86404
Office 928.505.2501 Fax 928.505.2503



Revision
1/11/11

2RZ/3RZ Teflon Throttle Body Gasket (Part #1032099)

On the Teflon throttle body gasket there is a small notch cut out of the center hole of the gasket. This notch must be installed as shown below. Failure to install it properly will result in running issues.



2031 Holly Avenue, Lake Havasu City, AZ 86404
Office 928.505.2501 Fax 928.505.2503